

SERIES C1200



- Absolute / relative positioning commands
- Limited jerk motion commands
- Time Curves
- Real Time (Streaming)
- Synchronous control (Drive profiles)
- PLC or Stand-Alone Solutions
- Digital and Analog IO's
- Safe Torque Off
- Interface for optional incremental or absolute sensor
- Supports Plug and Play
- CE/UL/CSA



Servo Drive C1200

Series C1200 servo drives are axis controllers, with 32-bit position resolution and an integrated power stage, for linear and rotary motors. The controllers are suitable for standard and high-end positioning tasks with NC Synchronisation.







CONNECTION TO MACHINE CONTROL

The Series C1200 servo drives can be actuated by machine controls from many manufacturers or brands, via digital inputs and outputs over Industrial Ethernet.

Bus-Interfaces:

- » ProfiNet / ProfiDrive
- » EtherCat, SoE, CoE
- » Ethernet IP
- » PowerLink
- » Sercos III

PROCESS AND SENSOR INTERFACES

Fast process interfaces for direct processing of sensor signals are available as freely programmable analog and digital inputs, a fast trigger input, and a capture input.

The safety IO's on Servo Drives with the -1S option with industrial ETHERNET allows safe torque off (STO) of the drives via control signals, without interrupting the power supply.

Drives with -0S option comes without safety IO's and is easier to wire in applications without safety needs.

LOGIC AND POWER SUPPLY

The servo drives have two separate inputs for the logic and motor elements.

This has the advantage that the drive and linear motor do not need to be reinitialized when the machine is restarted, since all process data, including the actual position of the linear motor, is still up to date




System Integration

Flexible hardware enables control of many 1/2/3-phase motors. Thus, low-power rotary servomotors, such as brushless DC motors, can be integrated in the same control concept.

Additionally, the drives can be equipped with optional peripherals, such as reference and end stop switches, high-precision external position sensors, or a mechanical holding brake.

Series C1200 servo drives have analog and digital inputs and outputs, serial interfaces, fieldbusses, and Ethernet. The user therefore is not dependent on the selection of the overlaid controller. An appropriate interface is available, with associated protocols, for many PLC or IPC solutions.

With flexibility and a compact form factor, LinMot Series C1200 servo drives provide a complete solution for a flexible drive concept in single and multiple axes applications, with linear motors and other actuators.



HIGH-END AND NC-MOTIONS

The ultra-fast control cycle together with the high resolution A/D converters of the C1200 series drives guarantee perfect motor control for demanding Positioning tasks.

The various drive profiles available on the series C1200 drives makes it easy to integrate these drives into systems with synchronized axes and overlaid NC-position controllers with industrial Ethernet communication.

MOTOR INTERFACES

C1200 servo drives provide all necessary interfaces to operate linear or rotary motors with optional external peripherals, such as end position and reference switches, a mechanical brake, or a high-resolution external position sensor.


CONFIGURATION

LinMot Talk, a user-friendly PC software is available for configuration. In addition to online documentation, LinMot Talk provides extensive debugging tools, such as an oscilloscope and an error inspector, for simple and rapid start-up of the Axis.

Fieldbus and Ethernet drives can also be configured directly by the overlaid control, by downloading the configuration parameters via Bus/Ethernet




INTERPOLATED MOVES



For direct position targets, using absolute or relative positioning, the desired position is reached using acceleration and velocity-limited motion profiles or jerk optimized profiles (example: Bestehorn). Positioning commands can be invoked via serial Ethernet or a trigger input.

 $\begin{array}{ll} \textbf{Stroke range:} & \pm 100 \text{ m} \\ \textbf{Position Resolution:} & 0.1 \, \mu \text{m} \, (32 \text{Bit}) \\ \textbf{Velocity Resolution:} & 1.0 \, \mu \text{m/s} \, (32 \text{Bit}) \\ \textbf{Acceleration Resol.:} & 10.0 \, \mu \text{m/s}^2 \, (32 \text{Bit}) \\ \end{array}$


TIME CURVES



Up to 100 different time curves can be stored on Series C1200 drives, with up to 16,000 individual waypoints. The motor can thus travel along time curves of any complexity, such as those generated by CAD programs and stored in the drive (Excel CSV format). The time curves can be invoked via the serial interface, fieldbusses, Ethernet, or the trigger input.

 $\begin{array}{lll} \textbf{Stroke range:} & \pm 100 m \\ \textbf{Position Resolution:} & 0.1 \, \mu m \, (32 Bit) \\ \textbf{Motion profiles:} & \text{Max. } 100 \, \text{Time Curves} \\ \textbf{Curve points:} & \text{Max. } 16'000 \, \text{points} \\ \end{array}$


PROFILED MOVES



For travel to an absolute position, or shifting by a relative position, any desired motion rules can be stored besides the VA interpolator. They are stored in the drive as motion profiles (Excel CSV format). The positions can be approached, for example, with a sinusoidal motion to optimize power loss, or special reverse optimized motion profiles.

 $\begin{array}{lll} \textbf{Stroke range:} & \pm 100 m \\ \textbf{Position Resolution:} & 0.1 \ \mu m \ (32 Bit) \\ \textbf{Motion profiles:} & \text{Max. } 100 \ \text{Time Curves} \\ \textbf{Curve points:} & \text{Max. } 16'000 \ \text{points} \\ \end{array}$

SETPOINT STREAMING



Overlaid NC drives with fieldbus or Ethernet interfaces communicate with the servo drives via "Position Streaming". The position and velocity calculated in the overlaid control is transmitted to the Servo Drive cyclically. The P, PV, or PVA mode is available for this transmission.

Position Resolution:32 BitVelocity Resolution:32 BitInterpolator:8 kHzCycle times:0.25 - 5 ms




EASY STEPS

Input 1	Pos 125 mm
Input 2	Pos 250 mm
Input 3	Curve 1
Input 4	Pos -30 mm

With the Easy Steps function, up to 4 positions or independent travel commands can be stored on the drive, and addressed via 4 digital inputs or fieldbus interfaces/Ethernet.

Digital inputs:4Interface:X4Scanning rate:250 μsec


COMMAND TABLE



Entire motion sequences with up to 255 individual motion commands can be stored in the Command Table. This is primarily advantageous if complete motion sequences need to be executed very quickly, without dead time from the overlaid PLC. In the Command Table, the programmer has access to all motion commands, internal parameters, and digital inputs and outputs.

Commands: max. 255
Cycle time: 125 µsec

ANALOG POSITION



For an analog position target, the linear motor travels to a position proportional to the input voltage. The position is either scanned continuously, or only after a rising edge of the trigger signal. In order to prevent uncontrolled jumps in position, the motor travels to the positions with a programmable maximum acceleration and velocity (VA interpolator).

Inputs: Analog Input X4


Voltage range: 0-10VDC or ±10V

Resolution: 12 Bit

Scanning rate: >=125 μsec (adjustable)

EASY STEPS PARAMETER SCALE

Maximum Force [0...10V => 0...100%]




Easy Steps provide the ability to parameterize internal parameters using two analog inputs. If, for example, the maximum motor current is read at an analog input, then the maximum motor force can be provided as analog for freely programmable joining processes.

Inputs:2 x AnalogVoltage range:0-10VDCResolution:12 BitScanning rate:250 µsec




CLOSED LOOP FORCE CONTROL



Using the force control technology function, precise joining processes can be implemented reliably and reproducibly with high-precision force control. For force control, the current motor force is measured with a load cell and controlled in the drive. Joining process or quality checks with high requirements for applied force can be implemented.

Analog input: 0-10V or ± 10 V Resolution: 12 Bit Min. Force Resolution: 0.1N





Interfaces	C1250-PN-XC	C1250-PD-XC	C1250-EC-XC	C1250-DS-XC	C1250-SE-XC	C1250-IP-XC	C1250-PL-XC	C1250-SC-XC	C1250-LU-XC
PROFINET	•								
PROFINET ProfiDrive		•							
ETHERCAT			•						
ETHERCAT CiA402				•					
ETHERCAT SoE					•				
ETHERNET IP						•			
POWERLINK							•		
SERCOS III								•	
LinUDP									•







POWERLINK




C1250-PN-XC C1250-EC-XC C1250-IP-XC C1250-PL-XC C1250-SC-XC

C1250-SE-XC C1250-PD-XC

C1250-DS-XC

C1250-LU-XC

- Absolute & Relative Positioning
- » Time based motion profiles
- » Internally stored Motion Sequences
- » Position Streaming
- » Analog Position Target
- » Analog Parameter Scaling
- » Force Control Technology Function
- Customer-Specific Functions



INDUSTRIAL ETHERNET

Series C1200 drives allow integration of Lin-Mot linear motors in controls concepts with industrial Ethernet interfaces. The user can integrate Series C1200 drives regardless of the provider of the overlaid control.

LinMot drives are available with common industrial Ethernet protocols. Since all Ethernet drives have the same motion command interface, and the control and status word are identical, software blocks that have been implemented once can be transferred to other drives without a problem.

The series C1200 servo drives support the following industrial Ethernet protocols:

Profinet

» EtherCAT

» Ethernet IP

» PowerLink

» Sercos III

» Sercos over EtherCAT

» ProfiDrive

» CiA 402

» LinUDP

The appropriate drive is available for each protocol.


TECHNICAL DATA

Type: Realtime ETHERNET
Switch/Hub: Integrated 2-Port
Hub/Switch
Transfer rate: 10/100MBit/sec

Minimal cycle times:


Bus cycle: 250 µs
IO update: 250 µs
Trigger Input: 125 µs
Position control loop: 125 µs
Current control loop: 62.5 µs








X1 + PE MOTOR SUPPLY / REGENERATION RESISTOR



Connector has to be ordered separately




Motor Supply: 72VDC nominal, 24...85VDC

Absolute max. Rating: 72VDC +20%. External Fuse: 16A slow-blow / min. 100VDC

If motor supply voltage exceeds 90VDC, the drive will go into error state.

- » Use 60/75°C copper conductors only
- » Conductor Cross-Section 2.5mm2 (AWG14) max Length 3 m

X2 MOTOR PHASES




Nr	Designation	LinMot Linear Motor	Color	3-Phase EC-Motor	Color
1	PH1+	Motor Phase 1+	red	Motor Phase U	red
2	PH1-	Motor Phase 1-	pink	Motor Phase V	pink
3	PH2+	Motor Phase 2+	blue	Motor Phase W	blue
4	PH2-	Motor Phase 2-	grey	Motor Phase X	grey
5	PE/SCR	Shield		Shield	

Connector has to be ordered separetely

- » Use 60/75°C copper conductors only
- » Conductor cross-section: 0.5 2.5mm2 (depends on Motor current) / AWG 21 -14

X3 MOTOR SENSOR / BRAKE




DSUB-9

	i	•	
Nr		LinMot Motor	EC Motor
1		Do not connect	Do not connect
	6	Brake+	Brake+
2		Do not connect	Do not connect
	7	Do not connect	KTY
3		+5VDC	+5VDC
	8	AGND	AGND
4		Sensor Sine	Sensor Sine / Hall Switch U
	9	Sensor Cosine	Sensor Cosine / Hall Switch V
5		Temp In	Hall Switch W
	Case	Shield	Shield

- » Use +5V (X3.3) and AGND (X3.8) only for motor internal hall sensor supply (max. 100mA)
- » Cable length < 30 m</p>
- » Brake+: 24V / max. 500mA, Peak 1.4mA (will shut down if exceeded)
- » Caution: Do NOT connect AGND (X3.8) to ground or earth!







Use Y-style motor cables only (for example K15-Y/C)! A W-style cable has a different shielding, so it cannot be modified to a Y-style cable!

X4 LOGIC SUPPLY / IO CONNECTION

DSUB-9 (f) Spring cage connector (has to be ordered separately)

Nr			
11	AnIn-	X4.11	Configurable Analog Input differential (with X4.10)
10	AnIn+	X4.10	Configurable Analog Input differential (with X4.11)
9	AnIn	X4.9	Configurable Analog Input single ended
8	In	X4.8	Configurable Input
7	In	X4.7	Configurable Input
6	In	X4.6	Configurable Input
5	In	X4.5	Configurable Input
4	Out	X4.4	Configurable Output
3	Out	X4.3	Configurable Output
2	+24VDC	Supply	Logic Supply 22-26 VDC
1	GND	Supply	Ground

Inputs: (X4.5...X4.8) Outputs: (X4.3 & 4.4) Analog inputs: X4.9: X4.10/X4.11:

Supply 24V:

24V / 5mA (Low Level: -0.5 to 5VDC, High Level: 15 to 30VDC) 24V / max. 500mA, Peak 1.4mA (will shut down if exceeded) 12 bit A/D converted.


Single ended analog input to GND, 0..10V, Input Resistance: $51k\Omega$ to GND Differential analog input, +/- 10V. Common mode range: +/- 5VDC to GND. Input Resistance: $11.4k\Omega$ for each signal to GND

typically 500mA / max. 2.5A (if all outputs "on" with max. load.)

- » Use 60/75°C copper conductors only
- » Conductor cross-section max. 1.5 mm²
- » Stripping length: 10 mm
- The 24VDC supply for the control circuit (X4.2) must be protected with an external fuse (3A slow blow)



X13 EXTERNAL POSITION SENSOR PIN CONFIGURATION



DSUB-15 (f)

Nr		ABZ with Hall Switches	SSI / BiSS / EnDat
1		+5V DC	+5V DC
	9	A+	A+
2		A-	A-
	10	B+	B+
3		B-	B-
	11	Z+	Data+
4		Z-	Data-
	12	Encoder Alarm	Encoder Alarm
5		GND	GND
	13	U+	nc
6		U-	nc
	14	V+	nc
7		V-	nc
	15	W+	Clk+
8		W-	Clk-
Case		Shield	Shield

Position Encoder Inputs (RS422):

Max. counting frequency: 25 M counts/s with quadrature decoding. A minimum of 40ns edge separation must be guaranteed by the encoder under any circumstances! The maximal frequency of each signal is 6.25 MHz.

Differential Hall Switch Inputs (RS422):

Enc. Alarm In: 5V / 1mA

Sensor Supply: 5VDC, max 100mA

X17 - X18 REALTIME ETHERNET 10/100 MBIT/S




RJ-45

Nr		
X17	RT ETH In	Specification depends on RT-Bus Type.
X18	RT ETH Out	Please refer to interface documentation.

Input Frequency: <1kHz

X19 SYSTEM



Nr		
1	(do not connect)	
2	(do not connect)	
3	RS232 RX	
4	GND	
5	GND	
6	RS232 TX	
7	(do not connect)	
8	(do not connect)	
case	Shield	

Use isolated USB-RS232 converter (Art.-No. 0150-2473) for configuration over RS232




SAFETY RELAYS (ONLY FOR -1S)

X33. 4/8 Ksr+ X33. 3/7 Ksr-X33. 2/6 Ksr f+ X33. 1/5 Ksr f-





Spring cage connector





- Use 60/75°C copper conductors only
- Conductor cross-section max. 1.5 mm²
- Stripping length: 10 mm
- Never connect the safety relays to the logic supply of the drive!

S1 - S2 ADDRESS SELECTORS



S1 (58)	Bus ID High (0 F). Bit 5 is the LSB, bit 8 the MSB.
S2 (14)	Bus ID Low (0 F). Bit 1 is the LSB, bit 4 the MSB

Setting the ID high & low to FF resets the drive to manfacturer settings!

The use of these switches depends on the type of fieldbus which is used. Please see the corresponding manual for further information.

BUS TERMINATION S5



Bootstrap (Internal use only)

Default position View: X13 Connecter is left next to \$5 switch

STATE DISPLAY



24VOK	Green	24V Logic Supply OK
En	Yellow	Motor Enabled / Error Code Low Nibble
Warn	Yellow	Warning / Error Code High Nibble
Error	Red	Error


RT BUS LEDS




BUS OK	Green	OK
BUS Error	Red	Error

The use of these LEDs depends on the type of fieldbus which is used. Please see the corresponding manual for further information.







Servo Drive Series		C12500S		C12501S
Width	mm (in)		25.3 (1.0)	
Height	mm (in)	166 (6.5)		176 (6.9)
Height with fixings	mm (in)	206 (8.1)		216 (8.5)
Depth	mm (in)		106 (4.2)	
Weight	g (lb)	630 (1.4)		700 (1.54)
Mounting Screws		2 x M5		2 x M5
Mounting Distance between screw holes	mm (in)	168 (6.61)		188 (7.4)
Case IP Code	IP		20	
Storage temperature	°C		-2540	
Transport temperature	°C		-2570	
Operating temperature	°C		040 at rated date 4050 with power derating	
Relative humidity			95% (non-condensing)	
Pollution	IEC/EN 60664-1		Pollution degree 2	
Shock resistance (16 ms)	-1S option			3.5g
Vibration resistance (10-200Hz)	-1S option			1g
Max. case temperature	°C		70	
Max. power dissipation	W		30	
Mounting place			in the control cabinet	
Mounting position			vertical	
Distance between Drives	mm (in)		Without Power Derating; 20 (0.8) left/right / 50 (2) top/bottom With Power Derating; 5 (0.2) left/right / 20 (0.8) top/bottom	



Servo Drives		
Item	Description	Part Number
C1250-PN-XC-0S-000	ProfiNet Drive (72V/25A)	<u>0150-1888</u>
C1250-PD-XC-0S-000	ProfiNet ProfiDrive (72V/25A)	<u>0150-2618</u>
C1250-EC-XC-0S-000	EtherCAT Drive (72V/25A)	<u>0150-1884</u>
C1250-DS-XC-0S-000	EtherCAT CoE Drive (72V/25A)	<u>0150-2415</u>
C1250-SE-XC-0S-000	EtherCAT SoE Drive (72V/25A)	<u>0150-1897</u>
C1250-IP-XC-0S-000	Ethernet/IP Drive (72V/25A)	<u>0150-1886</u>
C1250-PL-XC-0S-000	Powerlink Drive (72V/25A)	<u>0150-1885</u>
C1250-SC-XC-0S-000	Sercos III Drive (72V/25A)	<u>0150-1887</u>
C1250-LU-XC-0S-000	ETHERNET LinUDP Drive (72V/25A)	<u>0150-2491</u>
C1250-PN-XC-1S-000	Profinet Drive (72V/25A), STO	<u>0150-2348</u>
C1250-PD-XC-1S-000	ProfiNet ProfiDrive (72V/25A), STO	<u>0150-2619</u>
C1250-EC-XC-1S-000	EtherCAT Drive (72V/25A), STO	<u>0150-2345</u>
C1250-DS-XC-1S-000	EtherCAT CoE Drive (72V/25A), STO	<u>0150-2416</u>
C1250-SE-XC-1S-000	EtherCAT SoE Drive (72V/25A), STO	<u>0150-2350</u>
C1250-IP-XC-1S-000	Ethernet/IP Drive (72V/25A), STO	<u>0150-2346</u>
C1250-PL-XC-1S-000	Powerlink Drive (72V/25A), STO	<u>0150-2347</u>
C1250-SC-XC-1S-000	Sercos III Drive (72V/25A), STO	<u>0150-2349</u>
C1250-LU-XC-1S-000	ETHERNET LinUDP Drive (72V/25A), STO	<u>0150-2492</u>

Accessories			
Item	Description	Part Number	
DC01-CX000-0S/X1/X4	Connector set C12500S (X1, X4)	<u>0150-3527</u>	
DC01-CX000-1S/X1/X4/X33	Connector set C12501S (X1, X4, X33)	<u>0150-3528</u>	
DC01-C1X00/X1	Drive Connector for PWR 72DC Input	<u>0150-3525</u>	
DC01-CX000-X2	Motor connector (X2)	<u>0150-3526</u>	
DC01-Signal/X4	Drive Connector 24VDC & Logic	<u>0150-3447</u>	
DC01-Safety/X33	Drive Connector Safety	<u>0150-3451</u>	