



# **About Us**

UNIMOTION is a leading company in the industrial automation field, at a global level. Combining innovative engineering solutions – Unimotion helps companies of all sizes across a wide range of industrial segments. Unimotion develops Industry 4.0-enabled products and systems with leading quality, performance and value. Engineering, Production, Construction, Warehouse, Research & Development department; all this can be found under one roof. Thanks to years of experience and a consistent focus on automation technology, we are continually improving our products and implementing innovations that provide customers with many technical advantages. Our core values are precision, innovation, passion, and integrity. At Unimotion, our main goal is the satisfaction of every single customer with a commitment to deliver the impossible.

Unimotion sales team, technicians and experts are at your disposal to provide customized expertise and support. We look forward to meeting you and work on your special project.







# **Table of Contents**

General overview	4
Possible drive-motor-cable combinations	5
Speed-torque characteristics of possible drive-motor combinations	
Connections showcase	
Drives	7
How to order	8
Pulse-direction	
EtherCAT	
Ethernet	
Profinet	
- ·	0.4
Motors	24
How to order	25
STMN-42-L-E(-B)	25
STMN-56-L-E(-B)	
Cables	29
How to order	30
Power cable	31
Signal cable	31
Drive to motor cables	22

# **General overview**

Possible drive-motor-cable combinations	. 5
Speed-torque characteristics of possible drive-motor combinations	. 6
Connections showcase	e

UNIMOTION stepper motors and drives offer a simple solution for precise automation, available with Ethernet, EtherCAT, Pulse-direction or Profinet communication so that each application can be personalised according to individual specifications.





# POSSIBLE DRIVE-MOTOR-CABLE COMBINATIONS

In the table available motor-drive-cable combinations are shown.


Stepper motor		Dri	Drive Driver-to-motor cable		le		
Size [mm]	Brake	Code	Protocol/control	Code	Motor	Brake	Encoder
			EtherCAT	STDF-42-A-EC			
		STMN-42-L-E	Ethernet	STDF-42-A-EN	STCF-M12	_	STCF-E12
	_	STIVIN-42-L-E	Pulse-direction	STDF-42-A-PD			
□42			Profinet	STDL-40-C-PN	STCS-M12	_	STCS-E12
<b>□4</b> Z			EtherCAT	STDF-42-A-EC			
	with	STMN-42-L-E-B	Ethernet	STDF-42-A-EN	STCF-M12	STCF-B8	STCF-E12
	Witti	3 I WIN-42-L-E-D	Pulse-direction	STDF-42-A-PD	1		
			Profinet	STDL-40-C-PN	STCS-M12	STCS-B8	STCS-E12
		STMN-56-L-E	EtherCAT	STDF-56-A-EC			
			Ethernet	STDF-56-A-EN	STCF-M12	_	STCF-E12
	_	31 MIN-30-L-E	Pulse-direction	STDF-56-A-PD			
□56			Profinet	STDL-040-C-PN	STCS-M12	_	STCS-E12
□30			EtherCAT	STDF-56-A-EC	STCF-M12	STCF-B8	
		CTAIN ECLED	Ethernet	STDF-56-A-EN			STCF-E12
	with	STMN-56-L-E-B	Pulse-direction	STDF-56-A-PD			
			Profinet	STDL-040-C-PN	STCS-M12	STCS-B8	STCS-E12


# SPEED-TORQUE CHARACTERISTICS OF POSSIBLE DRIVE-MOTOR COMBINATIONS

i On the following diagrams torque as a function of speed is presented for each motor with appropriate drive.

STMN-42-L-E(-B) with STDF-42-A-.. or STDL-040-A-PN








# **CONNECTIONS SHOWCASE**


No.	Accessories	Page
1	Motor	<u>24</u>
2	Drive	<u>7</u>
3	Motor cable	<u>35</u>
4	Brake cable	<u>36</u>
5	Signal cable	<u>31</u>
6	Power cable	<u>31</u>
7	Encoder cable	<u>33</u>



# **Drives**

How to order	8
Pulse-direction	8
EtherCAT	12
Ethernet	16
Profinet	20

# **HOW TO ORDER**



<sup>1</sup> only available with Profinet comunication, oprating voltage option C and motor size option 040.

i For possible combinations refer to the table POSSIBLE DRIVE-MOTOR-CABLE COMBINATIONS, column Drive/Code.

#### **PULSE-DIRECTION**

#### **Description**

Pulse-direction refers to a type of digital signalling, used in position control. There are two types of pulse control:

- 1. 1-signal mode (Pulse/Mode) 2. 2-signal mode (CW/CCW)

This mode has CW and CCW inputs. The pulse at these inputs determines whether the motor rotates clockwise or counterclockwise.


It contains two signals, one for distance and speed, and the other for the direction of rotation. The actual movement is carried out by pulses received from the controller, i.e, can be arbitrarily set to be for one revolution of the motor, 1000 pulses.

#### Other advantages are:

- No gain tuning / No hunting
- Heat reduction / Torque improvement
- Plug & Drive (no tuning necessary)
- Brake control
- DIN rail mounting option
- RoHS directive
- EMC directive
- Closed-loop system (errors are corrected)



# **Dimensions**



8

#### General technical data

	Туре	Stepper drive
	Protocol/control	Pulse-direction control
	Code	STDF-PD
PARAMETER	UNIT	VALUE
Operating voltage	[V DC]	24 ± 10 %
Current consumption <sup>1</sup>	[mA]	max. 500
Rotational speed	[rpm]	Refer to chapter: SPEED-TORQUE CHARACTERISTICS
Supported resolution <sup>2</sup>	[ppr]	500, 1000, 1600, 2000, 3600, 5000, 7200, 10000
		Position command pulse
Input signals		Servo on/off
		Alarm reset (Photocoupler input)
		In-position
Output signals		Alarm (Photocoupler output)
		Encoder signal, brake
Ambient temperature	[°C]	0 ~ +50
Ambient humidity	[%]	35 ~ 80 (non-condensing)
Vibration resistance	[G]	0,5
Duty cycle	[%]	100

<sup>&</sup>lt;sup>1</sup> Except the motor current.


# Calculation of sufficient power supply:

$$P_{Wmax} = \left(I_d + I_{ph}\right) \cdot U_m$$

I <sub>ph</sub>	Motor phase current	[A]
I <sub>d</sub>	Drive current	[A]
U <sub>m</sub>	Power supply voltage	[V]
P <sub>Wmax</sub>	Maximum required power supply	[W]

i Required power supply P<sub>W</sub> is at maximum load of the stepper motor.

#### Port and indicator information




 $<sup>^2\,\</sup>text{For}$  the case that resolution is higher than the encoder's resolution, the motor shall operate by micro-step between pulses.

# Pin layout

# Input/Output signal connector (CN1):

No.	Function	1/0
1	CW+ (Pulse+)	Input
2	CW- (Pulse-)	Input
3	CCW+ (Dir+)	Input
4	CCW- (Dir-)	Input
5	A+	Output
6	A-	Output
7	B+	Output
8	B-	Output
9	l+	Output
10	I-	Output
11	Alarm	Output
12	In-position	Output
13	Servo on/off	Input
14	Alarm reset	Input
15	Open collector input	Input
16	BRAKE+	Output
17	BRAKE-	Output
18	S-GND	Output
19	EXT_GND	Input
20	EXT_24VDC	Input



# Motor connector (CN3):

No.	Function	I/O
1	A+ Phase	Output
2	B+ Phase	Output
3	A- Phase	Output
4	B- Phase	Output



# Power connector (CN4):

No.	Function	1/0
1	24 V (DC)	Input
2	GND	Input




# **Encoder connector (CN2):**

No.	Function	1/0
1	A+	Input
2	A-	Input
3	B+	Input
4	B-	Input
5	l+	Input
6	I-	Input
7	5 V (DC)	Output
8	GND	Output
9	F.GND	_
10	F.GND	_



10

# **External wiring diagram**



<sup>\*</sup>When connecting the I/O cables between the controller and drive, please turn off the power of both controller and drive to protect the drive from any damage.

# **CAUTION** =

Please refer to the Manual when connecting the motor extension cable.

Carefull connection will be required to protect the drive from any damages.

# **ETHERCAT**


#### **Description**

EtherCAT is the fastest Industrial Ethernet technology. This is a huge benefit for all applications in which the target system is controlled or measured via the bus system. The rapid reaction times work to reduce the wait times during the transitions between process steps, which significantly improves application efficiency.

- Other advantages:
   CiA 402 Drive Profile Support
- Closed-loop system (errors are corrected)
- No Gain Tuning / No Hunting
- Heat Reduction / Torque ImprovemPlug & Drive (no tuning necessary) Heat Reduction / Torque Improvement
- Brake control
- DIN rail mount option
- RoHS directive
- EMC directive



#### **Dimensions**



i All dimensions are in mm. The scale of the drawings may not be equal.

#### General technical data

	Туре	Stepper drive
	Protocol/control	EtherCAT
	Code	STDF-EC
PARAMETER	UNIT	VALUE
Operating voltage	[V DC]	24 ± 10 %
Current consumption <sup>1</sup>	[mA]	max. 500
Rotational speed	[rpm]	Refer to chapter: SPEED-TORQUE CHARACTERISTICS
Supported resolution <sup>2</sup>	[ppr]	500, 1000, 1600, 2000, 3600, 5000, 7200, 10000
Innut signals		3 dedicated inputs (LIMIT+, LIMIT-, ORIGIN)
Input signals		7 user inputs (Photocoupler)
Output signals		6 user outputs (Photocoupler)
Output signals		Brake
Ambient temperature	[°C]	0 ~ +50
Ambient humidity	[%]	35 ~ 80 (non-condensing)
Vibration resistance	[G]	0,5
Duty cycle	[%]	100

<sup>&</sup>lt;sup>1</sup> Except the motor current.


# Calculation of sufficient power supply:

$$P_{Wmax} = \left(I_d + I_{ph}\right) \cdot U_m$$

I <sub>ph</sub>	Motor phase current	[A]
I <sub>d</sub>	Drive current	[A]
U <sub>m</sub>	Power supply voltage	[V]
P <sub>Wmax</sub>	Maximum required power supply	[W]

i Required power supply P<sub>W</sub> is at maximum load of the stepper motor.

#### Port and indicator information




 $<sup>^2\,\</sup>text{For}$  the case that resolution is higher than the encoder's resolution, the motor shall operate by micro-step between pulses.

# Pin layout


#### Input/Output signal connector (CN1):


No.	Function	1/0
1	LIMIT+	Input
2	LIMIT-	Input
3	ORIGIN	Input
4	Digital In1	Input
5	Digital In2	Input
6	Digital In3	Input
7	Digital In4	Input
8	Digital In5	Input
9	Digital In6	Input
10	Digital In7	Input
11	Digital Out1	Output
12	Digital Out2	Output
13	Digital Out3	Output
14	Digital Out4	Output
15	Digital Out5	Output
16	Digital Out6	Output
17	BRAKE+	Output
18	BRAKE-	Output
19	EXT_GND	Input
20	EXT_24VDC	Input



#### EtherCAT ID display and settings switch (SW1, SW2):

There are two rotary switches for setting the value of the EtherCAT ID (ECAT Device ID) on the side of the device. The right switch (SW1) sets the »ones« (X1), while the switch on the left (SW2) sets the »tens«(X10). Set values are displayed on »ECAT ID« segment display.





#### **Encoder connector (CN2):**

No.	Function	1/0
1	A+	Input
2	A-	Input
3	B+	Input
4	B-	Input
5	l+	Input
6	I–	Input
7	5 V (DC)	Output
8	GND	Output
9	F.GND	_
10	F.GND	_



#### Motor connector (CN3):

No.	Function	I/O
1	A+ Phase	Output
2	B+ Phase	Output
3	A- Phase	Output
4	B- Phase	Output




# Power connector (CN4):

No.	Function	I/O
1	24 V (DC)	Input
2	GND	Input




#### EtherCAT communication connector (CN5, CN6):

No.	Function
1	TD+
2	TD-
3	RD+
4	-
5	-
6	RD-
7	-
Connection hood	F.GND



# **External wiring diagram**



<sup>\*\*</sup> When connecting the I/O cables between the controller and drive, please turn off the power of both controller and drive to protect the drive from any damage.

# **CAUTION** =

Please refer to the Manual when connecting the motor extension cable.

Carefull connection will be required to protect the drive from any damages.

# **ETHERNET**

# **Description**


Ethernet is the standard communication protocol used to connect devices. It is the most widely used technology for local area networking and allows TCP or UDP protocol for sending data (possible to control it with Siemens S7 PLC).

# Other advantages:

- Closed-loop system (errors are corrected)
- No Gain Tuning / No Hunting
  Heat Reduction / Torque Improvement
- Plug & Drive (no tuning necessary)
- Brake control
- DIN rail mount option
- RoHS directive
- EMC directive



#### **Dimensions**



i All dimensions are in mm. The scale of the drawings may not be equal.

#### General technical data

	Туре	Stepper drive	
	Protocol/control	Ethernet	
	Code	STDF-EN	
PARAMETER	UNIT	VALUE	
Operating voltage	[V DC]	24 ± 10 %	
Current consumption <sup>1</sup>	[mA]	max. 500	
Rotational speed	[rpm]	Refer to chapter: SPEED-TORQUE CHARACTERISTICS	
Supported resolution <sup>2</sup>	[ppr]	500, 1000, 1600, 2000, 3600, 5000, 7200, 10000	
Innut signals		3 dedicated inputs (LIMIT+, LIMIT-, ORIGIN)	
Input signals		9 programmable inputs (Photocoupler)	
		1 dedicated output (Compare out)	
Output signals		9 programmable outputs (Photocoupler)	
		Brake	
Ambient temperature	[°C]	0 ~ +50	
Ambient humidity	[%]	35 ~ 80 (non-condensing)	
Vibration resistance	[G]	0,5	
Duty cycle	[%]	100	

<sup>&</sup>lt;sup>1</sup> Except the motor current.


# Calculation of sufficient power supply:

$$P_{Wmax} = \left(I_d + I_{ph}\right) \cdot U_m$$

I <sub>ph</sub>	Motor phase current	[A]
I <sub>d</sub>	Drive current	[A]
U <sub>m</sub>	Power supply voltage	[V]
P <sub>Wmax</sub>	Maximum required power supply	[W]

i Required power supply P<sub>W</sub> is at maximum load of the stepper motor.

#### Port and indicator information




 $<sup>^2</sup>$  For the case that resolution is higher than the encoder's resolution, the motor shall operate by micro-step between pulses.

# Pin layout

#### Input/Output signal connector (CN1):

Function	I/O
LIMIT+	Input
LIMIT-	Input
ORIGIN	Input
Digital In1	Input
Digital In6	Input
Digital In7	Input
Compare out	Output
Digital Out1	Output
Digital Out2	Output
Digital Out3	Output
Digital Out4	Output
Digital Out5	Output
Digital Out6	Output
Digital In2	Input
Digital In3	Input
Digital In4	Input
Digital In5	Input
Digital In8	Input
Digital In9	Input
Digital Out7	Output
Digital Out8	Output
Digital Out9	Output
BRAKE+	Output
BRAKE-	Output
EXT_GND	Input
EXT_24VDC	Input
	LIMIT+ LIMIT- ORIGIN Digital In1 Digital In6 Digital In7 Compare out Digital Out1 Digital Out2 Digital Out3 Digital Out4 Digital Out5 Digital Out6 Digital In2 Digital In3 Digital In4 Digital In5 Digital In8 Digital In8 Digital In9 Digital Out7 Digital Out8 Digital Out7 Digital Out9 BRAKE+ BRAKE- EXT_GND



# Ethernet IP display and settings switch (SW1, SW2):

The value of the fourth digit of Ethernet IP can be set through the setting switch. Set the product's IP not to overlap with other connected products. The first, second and third values of the IP can be set through the GUI. Please refer to the manual for details. When the switch is set to 255 (FF), IP is set automatically, ignoring the setting (DHCP function). The fourth digit of the Ethernet IP is displayed on the 7-Segment display.





Ex) In case of Sw1:7 and Sw2:5 (5x16) + (7x1) = 87IP is to be set as 192.168.0.87

#### **Encoder connector (CN2):**

No.	Function	1/0
1	A+	Input
2	A-	Input
3	B+	Input
4	B-	Input
5	l+	Input
6	I-	Input
7	5 V (DC)	Output
8	GND	Output
9	F.GND	-
10	F.GND	-



#### Motor connector (CN3):

No.	Function	1/0
1	A+ Phase	Output
2	B+ Phase	Output
3	A- Phase	Output
4	B- Phase	Output




#### Power connector (CN4):

No.	Function	1/0
1	24 V (DC)	Input
2	GND	Input




#### Ethernet communication connector (CN5, CN6):

No.	Function
1	TD+
2	TD-
3	RD+
4	-
5	-
6	RD-
7	-
Connection hood	F.GND



# **External wiring diagram**



<sup>\*</sup>When connecting the I/O cables between the controller and drive, please turn off the power of both controller and drive to protect the drive from any damage.

Please refer to the Manual when connecting the motor extension cable.

Carefull connection will be required to protect the drive from any damages.

# **PROFINET**

# **Description**

The drives offer Profinet IRT communication and control via Siemens Tia Portal development environment. It allows updating the set points with a cycle time of less than 1 ms. STDL-PN drives offer improved speed-torque characteristics that make this stepper system versatile and usable in many applications.


- Other advantages:
   Profinet IRT communication
- Automatic Brake control
- Easy and fast mounting on the DIN rail
- Closed-loop system (errors are corrected)
- Free programming software





For configuration of the STDL drive STIL device is needed. STIL device connects to STIL port on STDL drive.




#### **Dimensions**









i All dimensions are in mm. The scale of the drawings may not be equal.

# **Technical data**

		Туре	Stepper	
		Protocol/control	Profinet	
		Code	STDL-040-C-PN	
	PARAMETER	UNIT	VALUE	
	Operating voltage	[V DC]	20 - 50	
	Motor current	[A]	1.0 - 4.5	
	Current consumption <sup>1</sup>	[mA]	max. 160	
ш	Rotational speed	[rpm]	Refer to chapter: SPEED-TORQUE CHARACTERISTICS	
	I/O signals		8 Digital inputs	
DRIV			3 Digital outputs	
			1 Analog input	
			1 Encoder Input A, B, I	
	Ambient temperature	[°C]	0-40	
	Ambient humidity	[%]	10-90	
	Vibration resistance	[G]	<1	


 $<sup>^{\</sup>rm 1}\,\text{Motor}$  current not included. @ 24 V DC

# Calculation of sufficient power supply:

$$P_W = 5 + \left(1.1 \cdot \left(I_{ph}^2 \cdot R_{ph}\right) + \left| \frac{\left(V_{rpm} \cdot T_{nm}\right)}{7} \right|\right)$$

I <sub>ph</sub>	Motor phase current	[A]
R <sub>ph</sub>	Motor phase resistance	[o]
V <sub>rpm</sub>	Rotation speed	[rpm]
T <sub>nm</sub>	Resistant torque of the load	[Nm]
Pw	Required power supply	[W]

# **Port information**



# Pin layout

#### Power connector (CN1):

No.	Function	1/0
1	+VDC	Input
2 GND		Input
1 2		

#### Motor connector (CN2):

No.	Function	I/O
1	A- Phase	Output
2	A+ Phase	Output
3	B+ Phase	Output
4	B- Phase	Output
5	Not connected	Output




#### Input output signal connector (CN3):

No.	Function <sup>2</sup>	1/0
1	+24 V (Auxiliary) <sup>1</sup>	Input
2	0 V (GND) (Auxiliary) <sup>1</sup>	Input
3	Digital In0+	Input
4	Digital In0-	Input
5	Digital In1+	Input
6	Digital In1-	Input
7	Digital common DI2DI4	Input
8	Digital In2	Input
9	Digital In3	Input
10	Digital In4	Input
11	Digital Out0+	Output
12	Digital Out0-	Output
13	Digital Out1+	Output
14	Digital Out1-	Output
15	Analog In0+	Input
16	Analog In0 (GND)	Input
17	Digital Out2+	Output
18	Digital Out2-	Output
19	Digital common DI5DI7	Input
20	Digital In5	Input
21	Digital In6	Input
22	Digital In7	Input

<sup>&</sup>lt;sup>1</sup>The auxiliary power supply is optional and, if provided, keeps the control section of the drive powered.

<sup>2</sup>The digital outputs do not have a specific functionality and their use depends on how the drive is configured. Digital output breakdown current is 120 mA.



#### **Encoder connector (CN4):**

No.	Function	I/O
1	5 V (DC)	Input
2	GND	Input
3	A+	Input
4	Α-	Input
5	B+	Input
6	B-	Input
7	l+	Output
8	I–	Output
9	Not used	_
10	Not used	_



# Profinet BUS (P1, P2):


The P1 and P2 connectors are used for connection to the PROFINET field bus. It is therefore possible to connect several drives in cascade without the need for external devices.


No.	Function
1	TD+
2	TD-
3	RD+
4	CT-T
5	CT-R
6	RD-
7	Not connected
8	Shield




# **External wiring diagram**


#### **Digital inputs**





# Digital outputs







i Digital output breakdown current is 120 mA.

#### Brake wiring:

Brake must be wired via the relay.




# Analog input:



# **Motors**

How to order	2!
STMN-42-L-E(-B)	2!
STMN-56-L-E(-B)	2

# **HOW TO ORDER**



# **STMN-42-L-E(-B)**


# **Description**

NEMA 17 (42 mm) size stepper motor with high torque and M12 connectors offers IP65 protection (except the shaft outlet) and 1.8° step angle (full step). A motor with brake is also available.




i Motor without the brake is shown.

#### **Dimensions**



#### Motor with a brake:



25

#### General technical data

	Parameter	Unit	Value
	Voltage	[V DC]	3,15
	Current per phase	[A]	1,8
	Mass moment of inertia	[kg cm²]	0,082 (0,095 <sup>2</sup> )
~	Holding torque <sup>1</sup>	[Nm]	0,5
MOTOR	Step angle	[°]	1,8 ± 5 %
	Resistance per phase	[Ω]	1,75 ± 10 %
	Inductance per phase	[mH]	3,3 ± 20 %
	Voltage constant	mV min <sup>-1</sup>	23
	Mass	[kg]	0,44 (0,57 <sup>2</sup> )

<sup>&</sup>lt;sup>1</sup> For the speed-torque characteristic, please refer to page 6.

<sup>&</sup>lt;sup>2</sup> For a motor with brake.

	Parameter	Unit	Value
ENCODER	Туре		Incremental
	Measuring principle		Opto-electrical
	Interface		Line drive
	Resolution	[cpr/ppr]	500/2000
	Operating voltage	[V DC]	5


	Parameter	Unit	Value
BRAKE <sup>1</sup>	Operating voltage	[V DC]	24 (+6/-10 %)
	Rated output	[W]	8
	Holding torque	[Nm]	0,4
	Mass moment of inertia	[kg cm²]	0,013

<sup>&</sup>lt;sup>1</sup> For a motor with brake.

	Parameter	Unit	Value
<u>S</u>	Temperature rise: (Motor standstill; for 2 phase energized)	[°C]	max. 80
	Ambient temperature	[°C]	-10 ~ +50
OPERATING CONDITIONS	Ambient humidity	[%]	max. 85 (non- condensing)
	Protection class		IP65
	Duty cycle	[%]	100
	Insulation resistance	[MΩ]	100
	Insulation class		B (max. 130 °C)
	Dielectric strength	[V AC]	500 for 1 minute

#### **Motor forces**

Permissible loads				
Axial load F <sub>a</sub> [N]		1	5	
Distance a [mm]	5	10	15	20
Radial load F <sub>r</sub> [N]	50	36	26	20



# Motor pin allocation

#### Motor connector

Connector type: M12 5-pole



Pin	Function	
1	A-	
2	A+	
3	B+	
4	B-	
5	Housing	

# **Encoder connector**

Connector type: M12 8-pole



Pin	Function
1	A+
2	A-
3	B+
4	B-
5	GND
6	I-
7	l+
8	VCC (5 V)
Housing	GND/Shielding

# Brake connector

Connector type: M8 3-pole



Pin	Function
1	Brake +24 V
3	Brake/GND
4	NC

i Valid only for the motors with brake: STMN-...-B

# STMN-56-L-E(-B)

# **Description**


NEMA 23 (56 mm) size stepper motor with high torque and M12 connectors offers IP65 protection (except the shaft outlet) and 1.8° step angle (full step). A motor with brake is also available.




i Motor without the brake is shown.

#### **Dimensions**

#### Motor without a brake:



#### Motor with a brake:



#### **Technical data**

	Parameter	Unit	Value
	Voltage	[V DC]	2,4
	Current per phase	[A]	4,2
	Mass moment of inertia	[kg cm²]	0,48 (0,501 <sup>2</sup> )
~	Holding torque <sup>1</sup>	[Nm]	1,8
MOTOR	Step angle	[°]	1,8 ± 5 %
MOM	Resistance per phase	[Ω]	0,58 ± 15 %
	Inductance per phase	[mH]	1,9 ± 20 %
ı	Voltage constant	mV min <sup>-1</sup>	32,5
	Mass	[kg]	1,14 (1,33 <sup>2</sup> )

 $<sup>^{\</sup>rm 1}\,\mbox{For the speed-torque}$  characteristic, please refer to page 6.

<sup>&</sup>lt;sup>2</sup> For a motor with brake.

	Parameter	Unit	Value
	Туре		Incremental
ER	Measuring principle		Opto-electrical
ENCOD	Interface		Line drive
ENG	Resolution	[cpr/ppr]	500/2000
	Operating voltage	[V DC]	5


	Parameter	Unit	Value
BRAKE <sup>1</sup>	Operating voltage	[V DC]	24 (+6/-10 %)
	Rated output	[W]	10
	Holding torque	[Nm]	1
	Mass moment of inertia	[kg cm²]	0,021

<sup>&</sup>lt;sup>1</sup> For a motor with brake.

	Parameter	Unit	Value
<u>S</u>	Temperature rise: (Motor standstill; for 2 phase energized)	[°C]	max. 80
0	Ambient temperature	[°C]	-10 ~ +50
OPERATING CONDITIONS	Ambient humidity	[%]	max. 85 (non- condensing)
	Protection class		IP65
	Duty cycle	[%]	100
	Insulation resistance	[MΩ]	100
	Insulation class		B (max. 130 °C)
	Dielectric strength	[V AC]	500 for 1 minute

#### **Motor forces**

Permissible loads				
Axial load F <sub>a</sub> [N]		1	5	
Distance a [mm]	5	10	15	20
Radial load F <sub>r</sub> [N]	130	90	70	52



# Motor pin allocation

#### Motor connector

Connector type: M12 5-pole



Pin	Function
1	A-
2	A+
3	B+
4	B-
5	Housing

# **Encoder connector**

Connector type: M12 8-pole



Pin	Function
1	A+
2	A-
3	B+
4	B-
5	GND
6	I-
7	l+
8	VCC (5 V)
Housing	GND/Shielding

# Brake connector

Connector type: M8 3-pole



Pin	Function
1	Brake +24 V
3	Brake/GND
4	NC


i Valid only for the motors with brake: STMN-...-B

# Cables


How to order	30
Power cable	31
Signal cable	31
Policy to an extended to	22

# **HOW TO ORDER**

# Power cables for the stepper drives (only for the STDF drives)




# Signal cables for the stepper drives (only for the STDF drives)




- PD: Pulse-direction control

# Drive-to-motor cables for the stepper motors (only for STDF/STDL drives and STMN motors)



# **POWER CABLE**

Connection cable between STDF drive and power supply.



Dimensions	Power cable
	STCF-P-02
L [m]	2
ØD [mm]	4,6

Wire code	Wire designation	Pin number
Red	+24 V DC	1
Black	GND	2

# **SIGNAL CABLE**


Connection cables between STDF drive and PLC/PC for different protocols.

Dimension	Signal cable		
Difficitsion	STCF-S-PD-02	STCF-S-EC-02	STCF-S-EN-02
L1 [m]	2		
ØD¹ [mm]	6,4	6,4	6,9

 $<sup>^{\</sup>rm 1}$  For symbol designation see the dimensional drawings of signal cables below.

#### **Pulse-direction**

Connection cable between the drive and PLC/PC for Pulse-direction based control.




Wire colour code	Wire designation
White, 1 red dot	Pulse+
White, 1 black dot	Pulse-
White, 2 red dots	Dir+
White, 2 black dots	Dir-
White, 3 red dots	A+
White, 3 black dots	A-
White, 4 red dots	B+

Wire colour code	Wire designation
White, 4 black dots	B-
White, 5 red dots	l+
White, 5 black dots	I-
Yellow, 1 red dot	Alarm
Yellow, 1 black dot	InPosition
Yellow, 2 red dots	ServoOff
Yellow, 2 black dots	AlarmRst

Wire colour code	Wire designation
Yellow, 3 red dots	(OCInput)
Yellow, 3 black dots	Brake+
Yellow, 4 red dots	Brake-
Yellow, 4 black dots	GND_S
Yellow, 5 red dots	GND_24 V
Yellow, 5 black dots	24 V DC
Shield	/

#### **EtherCAT**

Connection cables between the drive and PLC/PC for EtherCAT communication.




Wire colour code	Wire designation
White, 1 red dot	Limit+
White, 1 black dot	Limit-
White, 2 red dots	Origin
White, 2 black dots	ln1
White, 3 red dots	ln2
White, 3 black dots	ln3
White, 4 red dots	In4

Wire colour code	Wire designation
White, 4 black dots	ln5
White, 5 red dots	ln6
White, 5 black dots	In7
Yellow, 1 red dot	Out1
Yellow, 1 black dot	Out2
Yellow, 2 red dots	Out3
Yellow, 2 black dots	Out4

Wire colour code	Wire designation
Yellow, 3 red dots	Out5
Yellow, 3 black dots	Out6
Yellow, 4 red dots	Brake+
Yellow, 4 black dots	Brake-
Yellow, 5 red dots	GND_24 V
Yellow, 5 black dots	24 V DC
Shield	/

#### **Ethernet**

Connection cables between the drive and PLC/PC for Ethernet communication.



Wire colour code	Wire designation
White, 1 red dot	Limit+
White, 1 black dot	Limit-
White, 2 red dots	Origin
White, 2 black dots	ln1
White, 3 red dots	In6
White, 3 black dots	In7
White, 4 red dots	CmpOut
White, 4 black dots	Out1
White, 5 red dots	Out2

Wire colour code	Wire designation
White, 5 black dots	Out3
Yellow, 1 red dot	Out4
Yellow, 1 black dot	Out5
Yellow, 2 red dots	Out6
Yellow, 2 black dots	In2
Yellow, 3 red dots	In3
Yellow, 3 black dots	In4
Yellow, 4 red dots	In5
Yellow, 4 black dots	In8

Wire colour code	Wire designation
Yellow, 5 red dots	In9
Yellow, 5 black dots	Out7
Orange, 1 red dot	Out8
Orange, 1 black dot	Out9
Orange, 2 red dots	Brake+
Orange, 2 black dots	Brake-
Orange, 3 red dots	GND_24 V
Orange, 3 black dots	24 V DC
Shield	/

# **DRIVE-TO-MOTOR CABLES**

Drive-to-motor cables include encoder, motor and brake cables. All the cables are flexible and can be used in combination with energy chains. Available lengths of the cables are 3 m, 5 m or 10 m.


# **Technical data**

	Code	Diameter	Length	Min. bending	Temperature range	
Туре					Fixed	Flexing
			[m]	[mm]	[°C]	[°C]
	STCF-E-A12-xx	6,7		50,25	-40/+70	+5/+70
Encoder	STCF-E-S12-xx	6,7			-40/+/0	+3/+/0
Encoder	STCS-E-A12-xx	6,3		63	-20/+80	-25/+60
	STCS-E-S12-xx	6,3		03	-20/+80	-23/+00
	STCF-M-A12-xx	5,1		38,25	-40/+70	+5/+70
Motor	STCF-M-S12-xx	5,1	3/5/10			
MOTOL	STCS-M-A12-xx	5,7		57	-20/+80	-25/+60
	STCS-M-S12-xx	5,7		57	-20/+60	-23/+00
	STCF-B-A8-xx 4,5		22.72	40/170	15/170	
Brake	STCF-B-S8-xx	4,5		33,72	-40/+70	+5/+70
Diake	STCS-B-A8-xx	4,5		45	20/.00	E/160
	STCS-B-S8-xx	4,5			-20/+80	-5/+60


#### **Encoder cable**

Connection cables between the drive and motor encoder. Available with a straight and angled M12 connector on the encoder side. An angled connector is always positioned towards the shaft of the motor.

# STCF-E-A12-xx/ STCF-E-S12-xx (for STDF drives)




# STCS-E-A12-xx/ STCS-E-S12-xx (for STDL drives)



#### Cable pin allocation:


Pin number	Wire colour
1	white
2	brown
3	green
4	yellow
5	gray
6	pink
7	blue
8	red




#### Motor cable

Connection cables between the drive and motor. Available with a straight and angled M12 connector on the motor side. An angled connector is always positioned towards the shaft of the motor.

#### STCF-M-A12-xx/ STCF-M-S12-xx (for STDF drives)




# STCS-M-A12-xx/ STCS-M-S12-xx (for STDL drives)



# Cable pin allocation:


Pin number	Wire colour
1	brown
2	white
3	blue
4	black
5	gray




#### **Brake cable**

Connection cables between the drive and brake. Available with a straight and angled M8 connector on the motor side. Only for the motors with brake. An angled connector is always positioned towards the shaft of the motor.

#### STCF-B-A8-xx / STCF-B-S8-xx (for STDF drives)




#### STCS-B-A8-xx / STCS-B-S8-xx (for STDL drives)



# Cable pin allocation:


Pin number	Wire colour
1	brown
3	blue
4	black



# **Connector dimensions**

In the table below the dimensions of the connector cables in reference to the motors are presented.

	Connector size	Straight	Ang	gular	
		L1	L2	L3	
	M8	47	31	26	
	M12	55,5	40	31	



# UNIMOTION



Unimotion: March 2023

We cover all major markets. If you wish to contact us, send us an enquiry and we would be happy to assist you.

GERMANY	NORTH AMERICA
Unimotion GmbH	Unimotion North America, Inc
Waldstrasse 20	3952 Ben Hur Ave, Unit 5
D - 78736 Epfendorf	Willoughby, OH 44094
T +49 (0) 7404 930 85 60 F +49 (0) 7404 930 85 61	T: +1 440-525-9106
www.unimotion.de	www.unimotionusa.com
vertrieb@unimotion.de	info@unimotionusa.com